



Before



After



After

Replaced cave-like shower stall with 3/8" clear tempered glass shower door and panel.

Installed shower caddy for additional storage space in shower area.

Grab bars were added to shower door to accommodate future handicap needs.



Before



Before



After

Low threshold for added ease of entering shower was used to accommodate future handicap needs.


8"x12" porcelain wall tile was installed to match new floor tile.



Before

12" x 12" porcelain tile was laid on a 45-degree angle to break up straight lines and create openness in the room.

After



The clients needs for extra storage space were met by installing custom full overlay cabinetry that surrounded the sink and toilet area.

The sides of the custom cabinets were scribed to fit within the new walls.

Puck lights were installed over the sink cabinet to create task lighting.

During



After

